

Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com

Date received: 27/06/17

Date of issue: 26/07/17

Report consists of 6 test reports.

Defects before testing: None

Sample name: HARMO

OMP S.R.L.

VIA CA' LEONCINO, 2

31030 CASTELLO DI GODEGO (TV)

ITALIA

SAMPLE N° 234598

Overall dimensions: 500 x 490 x 790 (h) mm

List performed tests:

- 1. Backrest strength test Static ANSI-BIFMA X5.1-2017/6
- 2. Drop test Dynamic ANSI- BIFMA X5.1-2017/7
- 3. Seating durability test Cyclic ANSI-BIFMA X5.1-2017/10
- 4. Back durability test Cyclic-Type II and III ANSI-BIFMA X5.1-2017/15
- 5. Leg strength test-Front application ANSI-BIFMA X5.1-2017/17
- 6. Leg strength test- Side application ANSI-BIFMA X5.1-2017/17



This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

ing Director drea Giavon



Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com

SAMPLE N° 234598

Date of issue: 26/07/17

Sample weight: Not determined

Sample name: HARMO



Side view



Bottom view



Rear view



Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com



LAB N° 0027 Membro degli MRA EA, IAF e ILAC

TEST REPORT

234598 / 1

Date received: 27/06/17
Date of test: 24/07/17
Date of issue: 26/07/17
Sample name: HARMO



OMP S.R.L. VIA CA' LEONCINO, 2 31030 CASTELLO DI GODEGO (TV) ITALIA

Backrest strength test - Static ANSI-BIFMA X5.1-2017/6

Type of chair: Type III

Test results:

Back load N	Time of application (minutes)	Remarks
667	1	No defects
1.001	1	No defects

Test passed

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Managing Director Dr. Andrea Giavon



Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com



LAB N° 0027 Membro degli MRA EA, IAF e ILAC

TEST REPORT

234598 / 2

Date received: 27/06/17
Date of test: 24/07/17
Date of issue: 26/07/17
Sample name: HARMO



OMP S.R.L. VIA CA' LEONCINO, 2 31030 CASTELLO DI GODEGO (TV) ITALIA

Drop test - Dynamic - ANSI- BIFMA X5.1-2017/7

Height of drop: 152 mm above the uncompressed seat surface

Test results:

Bag weight kg	Number of drops	Remarks
102	1	No defects
136	1	No defects

Test passed

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Managing Director Dr. Andrea Giavon



Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com



LAB N° 0027 Membro degli MRA EA, IAF e ILAC

TEST REPORT

234598 / 3

Date received: 27/06/17
Date of test: 29/06/17
Date of issue: 26/07/17
Sample name: HARMO



OMP S.R.L. VIA CA' LEONCINO, 2 31030 CASTELLO DI GODEGO (TV) ITALIA

Seating durability test - Cyclic - ANSI-BIFMA X5.1-2017/10

Seat impact test

Height of drop: 36 mm above the uncompressed seat surface

Test results:

Mass of drop kg	Number of drops	Remarks
57	100.000	No defects

Front corner load-ease test - cyclic -off-center

Test results:

Seat load N	Number of cycles	Remarks
890	20.000	No defects

Test passed

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Managing Director Dr. Andrea Giavon



Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com



LAB N° 0027 Membro degli MRA EA, IAF e ILAC

TEST REPORT

234598 / 4

Date received: 27/06/17
Date of test: 17/07/17
Date of issue: 26/07/17
Sample name: HARMO



OMP S.R.L. VIA CA' LEONCINO, 2 31030 CASTELLO DI GODEGO (TV) ITALIA

Back durability test - Cyclic-Type II and III ANSI-BIFMA X5.1-2017/15

Type of chair: Type III

Test results:

10011000110.				
Number of cycles	Seat load kg	Force application points on the backrest	Backrest force N	Remarks
120.000	109	Center of the backrest	334	No defects

Test passed

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Managing Director Dr. Andrea Giavon



Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com



LAB N° 0027 Membro degli MRA EA, IAF e ILAC

TEST REPORT

234598 / 5

Date received: 27/06/17
Date of test: 24/07/17
Date of issue: 26/07/17
Sample name: HARMO



OMP S.R.L. VIA CA' LEONCINO, 2 31030 CASTELLO DI GODEGO (TV) ITALIA

Leg strength test-Front application ANSI-BIFMA X5.1-2017/17

Test results:

Leg	Applied load N	Load application points mm	Time of application minutes	Remarks
Right leg	334	38 from the bottom and 25 from the edge	1	No defects
Left leg	334	38 from the bottom and 25 from the edge	1	No defects

Leg	Applied load N	Load application points mm	Time of application minutes	Remarks
Right leg	503	38 from the bottom and 25 from the edge	1	No defects
Left leg	503	38 from the bottom and 25 from the edge	1	No defects

Test passed

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Managing Director Dr. Andrea Giavon



Testing site: via Braide Matte, 4 33048 San Giovanni al Natisone (UD) tel. +39 0432 747211 lab@catas.com



LAB N° 0027 Membro degli MRA EA, IAF e ILAC

TEST REPORT

234598 / 6

Date received: 27/06/17
Date of test: 24/07/17
Date of issue: 26/07/17
Sample name: HARMO



OMP S.R.L. VIA CA' LEONCINO, 2 31030 CASTELLO DI GODEGO (TV) ITALIA

Leg strength test- Side application ANSI-BIFMA X5.1-2017/17

Test results:

Leg	Applied load N	Load application points mm	Time of application minutes	Remarks
Front leg	334	38 from the bottom and 25 from the edge	1	No defects
Rear leg	334	38 from the bottom and 25 from the edge	1	No defects

Leg	Applied load N	Load application points mm	Time of application minutes	Remarks
Front leg	503	38 from the bottom and 25 from the edge	1	No defects
Rear leg	503	38 from the bottom and 25 from the edge	1	No defects

Test passed

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Managing Director Dr Andrea Giavon